PERSPECTIVE FRAMING DIAGRAM

ORIGINAL FRAMING SHOWN IN FULL LINE AND WITH WOOD INDICATION. FRAME PIECES OF OLD WOOD NOT PART OF THE ORIGINAL FRAME OR IN THEIR ORIGINAL POSITION ARE SHOWN IN FULL LINE ONLY ———
NEWER FRAMING IS INDICATED WITH A DOT LINE ·····
CHIMNEY & FIREPLACE IN A DOT-DASH LINE —·—·—



RIDGE JOINT 1



NOTE: ALL RAFTERS ARE HALF LAPPED & PEGGED AT RIDGE. THEY ARE TAPERED FROM AN AVERAGE OF 5"x5" AT PLATE TO AN AVERAGE OF 4"x4" AT RIDGE.



END RAFTER

TYPICAL RAFTER



UPPER PLATE
END WALLS



FRONT & REAR PLATE

NOTE: NOTCHES FOR PORCH RAFTERS ON FRONT PLATE ONLY.

JOINT 7





CEILING JOISTS

NOTE: NOTCHES FOR PORCH JOISTS ON FRONT STUDS ONLY. FORMER PORCH PART OF THE ORIGINAL FRAME.



TYPICAL STUD

CORNER JOINT 2

LOWER PLATE



CORNER POST



CROSS BRACE

JOINT 5



NOTE: LEANTO RAFTERS ARE PEGGED INTO PLATE. THE PLATE IS NOT NOTCHED.

PLATE JOINT 3



WINDOW FRAMING



STUD



END WALL SILL



FRONT SILL

STUD JOINT 8

INDSIDE FACE

NOTCHED PLATE 4



PLATE IS SHOWN WITH THE UNDER-SIDE UP TO REVEAL THE MORTISES FOR FORMER STUDS & CUT FOR FORMER WINDOW FRAME.



DOOR HEAD



DOOR FRAMING

DOOR & WINDOW FRAMING JOINT 6

SILL JOINT 9

EXPLODED JOINTS

NOTE: JOINTS ARE DIAGRAMMATIC AND ARE NOT TO SCALE. ALL DIMENSIONS INDICATED ARE AVERAGE SIZES. ORIGINAL FRAME PIECES ARE OF CHESTNUT. OLD FRAMING NOT PART OF THE ORIGINAL FRAME ARE ALSO CHESTNUT. NEW FRAMING PIECES ARE GENERALLY PINE.

F.C. GJESSING DEL.

FIELD OFFICE SARATOGA NATIONAL HISTORIC PARK UNDER DIRECTION OF UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE, BRANCH OF PLANS AND DESIGN	NAME OF STRUCTURE JOHN NEILSON HOUSE BEMIS HEIGHTS, SARATOGA NATIONAL HISTORICAL PARK, STILLWATER, SARATOGA COUNTY, NY	SURVEY NO. NY-3317	HISTORIC AMERICAN BUILDINGS SURVEY SHEET 1 OF 3 SHEETS	LIBRARY OF CONGRESS INDEX NUMBER